

Reliable Home Inspection
719 237-3935
reliablehomeinspector57.com

Reliable Home Inspection

Radon Sampling Report

Test Address: 2131 Sunshine Ave Colo. Spgs; CO 80909

Test Location: Basement bedroom

Test Start Time: 8/25/21 @ 9:30 am

Test End Time: 8/27/21 @ 12:00 pm

Monitor #1: 5.3 pCi/L

Monitor #2: 5.4 pCi/L

Test Results: 5.35 pCi/L

The residence described above has been short term protocol tested (48 hours) for the presence of radon. The test and analysis have been performed in accordance with the Environmental Solutions Association (ESA) radon testing protocol. The Test Results represents the average radon concentration at the time the sampling was conducted and at the specific location within the building. Please note that radon concentrations will vary from day to day and from season to season.

The Environmental Protection Agency recommends mitigation action be taken for test results of 4.0 pCi/L or higher. Please visit www.epa.gov/radon for more information.